

KIT LIST REQUIREMENTS FOR ELECTRIC DEPARTMENT

REQUIRED TOOLS

- Green Patch Safety Boots
- Safety glasses
- Safety harness/lanyard
- Olfa Knife
- Pocket flashlight/headlamp
- 8" crescent wrench
- Circuit tester
- Non-contact voltage tester
- Leather/rubber workgloves
- Multidriver
- Needle nose pliers or multitool (Leatherman)
- Felt tip marker (ex. Sharpie)
- Tool belt
- Allen keys
- Electrical tape
- Multi-meter

GENNY OP KIT LIST:

- Green Patch Safety Boots
- Mutli-meter
- Circuit Tester
- Non-Contact Circuit Tester
- Various Tools for General Maintenance of Generators (such as wrenches and screwdrivers)
- Various Specialized grounding clamps and devices
- Pole Driver (for driving ground rods)
- Spade shovel (for installing ground plate)

* 269E Certification is highly recommended

**Weather gear (including extras) for all seasons is required